# gtRootbarrier Installation Guide

Installation Steps:

1. Dig a trench or tree hole
2. Roll out gtRootbarrier beside the trench or the tree hole and cut to the right length.
3. For trench planting over 50m in length, use a 1m overlap and butyl joining tape to secure 2 sheets of gtRootbarrier.
4. For planting around tree, shrubs or plants utilise a 50cm overlap and butyl joining tape to secure 2 sheets of gtRootbarrier.
5. Place gtRootbarrier with its smooth, coated side towards the roots of the tree.
6. Check overlaps, joins and position of gtRootbarrier
7. Fill in the trench or tree hole.

These are general instructions. The installer will have to make allowances for local conditions.

Rootbarrier Joining Guide:

Rootbarrier ®Applications: